## **Manual Honing tools RM004D**





Fix the honing tool on the

lathe or a drilling machine

First step:



Adjust the expension



Third step:

Insert the part on the honing tool



Forth step:

Move back and forth the part



Fifth step:

Measure the part and return to the second step if necessary

Typical use : rough machining and finishing of diameter, surface roughness improvement

Typical quantities : < 10 parts

Necessary equipment : lathe or drilling machine

Typical application : injection molding tools pins, extractors, clamping system, ...